

Abstract

Method for removing gasket material from a surface using nonwoven, three dimensional fibrous web articles employ phenolic particles.

1. A method for removing gasket material from a surface using nonwoven, three dimensional fibrous web articles employ phenolic particles.